UTAH STATE ENGINEER DAM INSPECTION REPORT

OWNER OF DAM Merrill R. MacDona 15
ADDRESS Kanab, let.
NAME OF DAM
ESTIMATED LOCATION: SEC. 16 TWP 395 RNG. 6 W. USBM SLBM
RESERVOIR CAPACITY ACFT. SURFACE AREA ACS.
TYPE: EARTH-FILL CONCRETE MASONRY OTHER
HEIGHT FEET, CREST LENGTH FEET
CREST WIDTH 450 FEET
SPILLWAY DIMENSIONS 3/X3/
APPROXIMATE SLOPE (IF EARTH): UPSTREAM DOWNSTREAM
GENERAL CONDITION
CONDITION REQUIRING REPAIR The dyte Needs Some Repair it has Settled for Some distance on the Lower Edge for about 100ft in length. I would say about 6" setteling,